

 **Federal Ministry**  
**Republic of Austria**  
Climate Action, Environment,  
Energy, Mobility,  
Innovation and Technology

Ministerstwo Infrastruktury i Budownictwa (MIB), State  
Commission on Aircraft Accident Investigation (SCAAI), Poland  
Patrycja Pacak  
ul. Chałubińskiego 4/6  
00-928 Warszawa  
POLAND

[bmk.gv.at](http://bmk.gv.at)

BMK - IV/SUB/ZLF (SUB-Fachbereich Zivilluftfahrt)  
[fus@bmk.gv.at](mailto:fus@bmk.gv.at)

**Ing. Oliver Bruck**  
Official in Charge

[oliver.bruck@bmk.gv.at](mailto:oliver.bruck@bmk.gv.at)

+43 (1) 71162 65 9103

Postal address: PO.Box 201, 1000 Vienna

Address: Radetzkystraße 2, 1030 Vienna

E-mail replies should be sent to the above e-mail  
address, quoting the reference number

Reference number: 2020-0.543.445

Vienna, 10.09.2020

**Accident with the Glider MDM-1 Fox, 01.09.2019,  
16:19 UTC, at Priel, Municipality Wolfsberg,  
A-9400, Carinthia**

Dear Sir/Madam,

In accordance with Art. 5 Regulation (EU) No 996/2010 on the investigation and prevention of accidents and incidents in civil aviation the aforementioned accident was subject of a safety investigation by the civil aviation safety investigation authority of Austria.

In accordance with Art. 16 (1) Regulation (EU) No 996/2010 the safety investigation is concluded with the enclosed report, which protects the anonymity of any individual involved in the accident.

In accordance with Art. 16 (6) Regulation (EU) No 996/2010 the Final Report will be made publicly available on the website of the safety investigation authority of Austria  
<https://www.bmk.gv.at/sub.html>.


The report contains safety recommendations.

In accordance with Art. 18 (1) Regulation (EU) No 996/2010 the addressee of a safety recommendation shall acknowledge receipt of the transmittal letter and inform the safety investigation authority which issued the recommendation within 90 days of the receipt of that letter, of the actions taken or under consideration, and where appropriate, of the time necessary for their completion and where no action is taken, the reasons therefor.

The Final Report is available in German language only.

*Enclosure (Final Report)*

The Head of the Safety Investigation Authority  
Sicherheitsuntersuchungsstelle des Bundes  
Die Leiterin:  
Hofrätin Dipl.-HTL-Ing. Bettina Bogner, BA, MA

Hinweis	Dieses Dokument wurde amtssigniert.	
	Datum	2020-09-15T08:59:54+02:00
	Seriennummer	1871969199
Aussteller-Zertifikat	CN=a-sign-corporate-05,OU=a-sign-corporate-05,O=A-Trust Ges. f. Sicherheitssysteme im elektr. Datenverkehr GmbH,C=AT	
Prüfinformation	Informationen zur Prüfung des elektronischen Siegels bzw. der elektronischen Signatur finden Sie unter: <a href="https://www.signaturpruefung.gv.at/">https://www.signaturpruefung.gv.at/</a>	

## Wojtasiak Wiesław

---

**Od:** Czerny Astrid <Astrid.Czerny@bmk.gv.at>  
**Wysłano:** 15 września 2020 09:01  
**Do:** SekretariatPKBWL; Pacak Patrycja  
**Temat:** Accident with the Glider MDM-1 Fox, 01.09.2019, at Priel, Municipality of Wolfsberg, A-9400, Carinthia  
**Załączniki:** 2020-0.543.445-3-A\_-\_Forwarding\_the\_Final\_Report\_15.09.2020\_MIB,\_SCAAI,\_Poland\_POLAND-00-928Warszawa.pdf; Endbericht\_MDM1-Fox\_final\_.pdf

Dear Ladies and Gentlemen,

attached we would like to forward the Final Report of the accident mentioned in the subject.

Yours sincerely

**Republic of Austria**  
**Federal Ministry for Climate Action, Environment, Energy, Mobility, Innovation and Technology**  
Sektion IV – Transport  
Federal Safety Investigation Authority

**Astrid Czerny**

+43 1 711 62-659231  
mobile: +43 664 837 34 06  
Radetzkystraße 2, 1030 Vienna, Austria  
[astrid.czerny@bmk.gv.at](mailto:astrid.czerny@bmk.gv.at)  
[www.bmk.gv.at/](http://www.bmk.gv.at/) [infothek.bmk.gv.at](http://infothek.bmk.gv.at)

